

Appendix A
Mine Reclamation Photos



Dangerous Vertical Openings at Cerrillos Mine Safeguard Project.
(Both Opening are High Priority Hazards)



Appendix A
Mine Reclamation Photos



Madrid Reclamation Project – Post-Reclamation Revegetation Success

Madrid Reclamation Project – Post-Reclamation Terrace / Stabilization of Coal Waste Pile.



Appendix A
Mine Reclamation Photos



Madrid Drain Project

Top Photograph:
Pre-construction or Existing Drain
Inlet. (On the left is Mr. Bob
Evetts, New Mexico AML
Program Manager)

Bottom Photograph:
Post-construction Drain Inlet.



Madrid Road (Highway) Drainage after construction.



Madrid Drainage near Inlet into Arroyo.

