



AMDTreat Beta 6.0 Install Instructions

Prior to installing and running AMDTreat Beta 6.0, the following prerequisites **must** be installed:

- Microsoft .NET Framework 4.8 (x86 and x64) [Download here](#)
- Install IPhreeqc Modules (Windows COM 32 bit/64 bit) [Download here](#)

After users have downloaded and installed the mandatory pre-requisites above, download AMDTreat 6.0 Beta.zip from our Sharefile site located here: [Office of Surface Mining \(sharefile.com\)](#). Once downloaded, users should unzip the file to a directory on their local drive, and then find the file called **AMDTreat 6.0 Beta.exe** and double click on it to run it. The screenshot below shows the directory tree that will be created and the location of the executable file.

Name	Date modified	Type	Size
.vs	3/11/2022 8:13 AM	File folder	
app.publish	3/4/2022 2:00 PM	File folder	
Data	3/4/2022 2:00 PM	File folder	
Images	3/4/2022 2:00 PM	File folder	
AMDTreat 6.0 Beta.application	3/4/2022 1:39 PM	Application Manif...	2 KB
AMDTreat 6.0 Beta.exe	3/4/2022 1:39 PM	Application	8,460 KB
AMDTreat 6.0 Beta.exe.config	2/8/2022 10:03 AM	XML Configuratio...	1 KB
AMDTreat 6.0 Beta.exe.manifest	3/4/2022 1:39 PM	MANIFEST File	15 KB
AMDTreat 6.0 Beta.pdb	3/4/2022 1:39 PM	Program Debug D...	6.614 KB

Optional – create a shortcut on your desktop:

Go to the directory that you installed the program to and find the file named AMDTreat 6.0 Beta.exe. Right click on the file and select “copy” from the menu. Go to your desktop and right click in any spot on your desktop. Select “paste shortcut” from the menu. You can now run the program from this icon that has been created on your desktop.