

FEDERAL REGISTER: 43 FR 46048 (October 5, 1978)

DEPARTMENT OF THE INTERIOR

AGENCY: Office of Surface Mining Reclamation and Enforcement (OSM)

30 CFR Part 715

Surface Coal Mining Reclamation and Reclamation Operations; Appendix -- Alluvial Valley Floors Technical Guidelines; Public Hearing; Correction

ACTION: Corrections.

SUMMARY: This document corrects the proposed Technical Guidelines that begin on page 38035 of the FEDERAL REGISTER of August 25, 1978, from Doc. 78-23668.

ADDRESSES: Regional Director, Office of Surface Mining Reclamation and Enforcement, Region V, 1823 Stout Street, Denver, Colo. 80202.

FOR FURTHER INFORMATION CONTACT:

John Hardaway, Office of Surface Mining and Enforcement, Region V, 1823 Stout Street, Denver, Colo. 80202, 303-837-5511. Additional copies may be obtained from Mr. Hardaway.

WALTER N. HEINE, *Director*.

The following corrections are made:

1. On page 38036, "Introduction", quotation of the 1st paragraph line 16 of the quotation "granting areas would be removed from use", is corrected to read "grazing areas would be removed from use."
2. On page 38036, "Introduction", 6th paragraph, which begins "Relevant sections of the law include:" and in particular, line 3 of subparagraph (3), "No permit or revision application affirma-" is corrected to read "No permit or revision application shall be approved unless the application affirma-." The corrected line is the 20th line from the bottom of page 38036 in the third column.
3. On page 38040, section I.A. Geomorphic Characteristics -- Relationship of surface landform (terrace) to underlying material (valley fill)", first full paragraph in the second column, line 2, "are found in flatlying of terraces." is corrected to read "are found in flatlying valley fills and there is no development of terraces."
4. On page 38040, section "I.A. Geomorphic Characteristics -- Relationship of surface landform (terrace) to underlying material (valley fill)", first full paragraph in the second column, line 17 (last line), "stream side area alluvial valley floor.", is corrected to read, "stream side area shall not be mapped as an alluvial valley floor.
5. On page 38041, section "I.B. Water Availability Characteristics -- Guideline Procedure I.B.2. Discussion", line 4, "sufficient for floor irrigation or subirriga-", is corrected to read, "sufficient for flood irrigation or subirriga-".

[FR Doc. 78-28238 Filed 10-4-78; 8:45 am]

BILLING CODE [4310-05]