



Photo Number 2

This is a typical view of the main refuse area before reclamation. Household debris, logging debris and light industrial debris had been dumped on the site. Many of the pits shown had vertical walls in excess of 20 feet high.