



Photograph Number 4

This is the dangerous Impoundment. All-terrain vehicles were traveling at the edge of the pond. Visitors were also using the site for swimming and fishing.